

# State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Supervisor DRH

# Inspection Report Minerals Regulatory Program Report Date: June 24, 2005

Mine Name: ML 48572-MP Operator or Permittee Name: Dell Pulsipher Permittee Mailing Address:	Permit number: S/053/063 Inspection Date: June 21, 2005			
Inspector(s): Doug Jensen Other Participants: Dell Pulsipher	Inspecti	r: Cloudy, Ho on Start Tim on End Time	<b>e:</b> 12:00	
Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds				
2. Public Safety (open shafts, adits, trash, signs, highwalls)				
3. Protection of Drainages				
4. Explosives, magazines	H	H	H	H
5. Deleterious Material	H	H	H	H
6. Roads (maintenance, surfacing, dust control,				
safety)				
7. Concurrent Reclamation				
8. Erosion Control				
9. Demolition				
10. Backfilling and Grading (trenches, pits,				, 🔲
roads, highwalls, shafts, drill holes)				
11. Water Impoundments				

## **Purpose of Inspection:**

16. Other: Inspect & Close

12. Soils

13. Revegetation14. Air Quality15. Facilities

The operator requested that the Division inspect and close this permit.

### **Inspection Summary:**

Mr. Pulsipher drove me to several areas within the lease where he had removed rock. None of the areas showed any effect from his rock removal activities. He had only removed surface rock and there was no evidence of any excavations. His method of operations resulted in very low impacts to the vegetation; therefore, the vegetation has



Inspection Date: June 21, 2005; Report Date: June 24, 2005

Page 2 of 2 S/053/063

recovered nicely in the areas where rocks had been removed. He has not removed any rock from this site in several years since he lost his SITLA lease.

### Conclusions/Recommendations:

This permit can be closed.

Inspector's Signature

Date: June 24, 2005

DJ:jb

Enclosures: photos

cc: Dell Pulsipher, Operator

John Blake, SITLA (ML 48572-MP)

O:\M053-Washington\S0530063-ML48572\Inspections\06212005insp.doc